



## !! URGENT !!

**Date:** 19 January 2021

**Subject:** Madinah, Saudi Arabia  
Prince Mohammad Bin Abdulaziz Intl (OEMA)  
Multiple procedures  
Cycle 2101

***Altitude incorrect***

Jeppesen NavData for cycle 2101, effective 28 January 2021 respectively, contains incorrect altitude at waypoint **D215T** for the **SISUD 1D [SISU1D] SID** and **SISUD 1P [SISU1P] SID** at Prince Mohammad Bin Abdulaziz Intl; Madinah, Saudi Arabia (OEMA).

Crossing altitude at waypoint **D215T** should be **at or above 13000'**.

### **WE STRONGLY URGE YOU TO MAKE THIS INFORMATION AVAILABLE TO APPROPRIATE CREW MEMBERS OR CUSTOMERS IMMEDIATELY!**

Revised coding will appear in Jeppesen NavData for cycle 2102, effective 25 February 2021. Until then an entry will appear in the NavData Change Notices, and this Alert will be posted on the Jeppesen Web site: [Notices and Alerts](#).

Please refer to the Prince Mohammad Bin Abdulaziz Intl; Madinah, Saudi Arabia (OEMA) 10-3M and 10-3Q charts dated 22 JAN 21 (effective 28 January 21) for valid information.

If you have questions concerning this NavData Alert, please contact Jeppesen Technical Support at:  
+1-303-328-4445 (Western Hemisphere)  
+49 610 250 8175 (Eastern Hemisphere)  
E-mail: [navdatatechsupport@jeppesen.com](mailto:navdatatechsupport@jeppesen.com)

NavData Alerts are published to advise users of significant issues in Jeppesen navigation data which may affect flight operations or safety. Different avionics equipment and computer systems use and display NavData and data derived from NavData differently. End NavData users should consult with their Avionics Provider for definitive information on whether their system is affected by this Alert.