



## **!! URGENT !!**

**Date:** 15 October 2021

**Subject:** Algiers, Algeria  
Houari Boumediene (DAAG)  
VOR DME ILS Rwy 23  
VOR DME Rwy 05  
VOR DME Rwy 23  
Cycle 2110

***Procedure coding outdated***

Jeppesen NavData for cycle 2110, Effective 7 October 2021, contain outdated procedure coding for Houari Boumediene; Algiers, Algeria (DAAG). ALGERIA AMDT 004-21, dated 11 OCT 21 was received after the ICAO specified date for aeronautical information publication.

Procedures **VOR DME ILS Rwy 23**, **VOR DME Rwy 05** and **VOR DME Rwy 23** have been completely revised and should not be used.

**WE STRONGLY URGE YOU TO MAKE THIS INFORMATION AVAILABLE TO APPROPRIATE CREW MEMBERS OR CUSTOMERS IMMEDIATELY!**

Revised coding will appear in Jeppesen NavData for cycle 2111, effective 4 November 2021. Until then an entry will appear in the NavData Change Notices beginning and this Alert will be posted on the Jeppesen Web site: [Notices and Alerts](#).

If you have questions concerning this NavData Alert, please contact Jeppesen Technical Support at:  
+1-303-328-4445 (Western Hemisphere)  
+49 610 250 8175 (Eastern Hemisphere)  
E-mail: [navdatasupport@boeing.com](mailto:navdatasupport@boeing.com)

NavData Alerts are published to advise users of significant issues in Jeppesen navigation data which may affect flight operations or safety. Different avionics equipment and computer systems use and display NavData and data derived from NavData differently. End NavData users should consult with their Avionics Provider for definitive information on whether their system is affected by this Alert.