



JEPPESEN[®]
NavData[®] Alert

!! URGENT !!

Date: 16 January 2019

Subject: Neuquen, Argentina
Presidente Peron (SAZN)
VOR Rwy 27
Cycle 1901

Incorrect Fix Position

Jeppesen NavData cycle 1901, effective 3 January 2019, contains incorrect data. The position/coordinates for the fix the fix ZN031 are incorrect.

The fix ZN031 should be NEUQUEN (NEU) VOR DME R-151/D13.0: coordinates S39 08 42.89 W068 01 57.48.

WE STRONGLY URGE YOU TO MAKE THIS INFORMATION AVAILABLE TO APPROPRIATE CREW MEMBERS OR CUSTOMERS IMMEDIATELY!

Revised coding will appear in Jeppesen NavData for cycle 1902, effective 31 January 2019. Until then an entry will appear in the NavData Change Notices, and this Alert will be posted on the Jeppesen Web site. <http://www.jeppesen.com/company/alerts/alerts.jsp>

Please refer to the Presidente Peron; Neuquen, Argentina (SAZN) 13-3 chart dated 5 OCT 2018 (effective 11 Oct 2018) for valid information.

If you have questions concerning this NavData Alert, please contact Jeppesen Technical Support at:

Phone: 1-303-328-4445

E-mail: navdatatechsupport@jeppesen.com

NavData Alerts are published to advise users of significant issues in Jeppesen navigation data which may affect flight operations or safety. They are distributed to affected ARINC 424 NavData users (avionics companies and other raw data users) and airlines receiving NavData directly from Jeppesen. Alerts are not distributed by Jeppesen to individual airline, business aviation or general aviation pilots, but are available to them on the Jeppesen Web site, www.jeppesen.com. Different avionics equipment and computer systems use and display NavData and data derived from NavData differently. Avionics users should consult with their database update service provider for definitive information on whether their system is affected by this Alert.