



## !! URGENT !!

**Date:** 04 January 2019

**Subject:** Weihai, PR of China  
Dashuipo (ZSWH)  
RNAV ILS DME Z Rwy 03  
Cycle 1901

***Approach transition identifier incorrect***

Jeppesen NavData for cycle 1901, effective 03 January 2019, contains an incorrect approach transition identifier for the **RNAV ILS DME Z Rwy 03** at Dashuipo; Weihai, PR of China (ZSWH):

Approach transition identifier **WEH** should be identified as **WH106**.

### **WE STRONGLY URGE YOU TO MAKE THIS INFORMATION AVAILABLE TO APPROPRIATE CREW MEMBERS OR CUSTOMERS IMMEDIATELY!**

Revised coding will appear in Jeppesen NavData for cycle 1902, effective 31 January 2019. Until then an entry will appear in the NavData Change Notices, and this Alert will be posted on the Jeppesen Web site: [Notices and Alerts](#).

If you have questions concerning this NavData Alert, please contact Jeppesen Technical Support at:  
+1-303-328-4445 (Western Hemisphere)  
+49 610 250 8175 (Eastern Hemisphere)  
E-mail: [navdatatechsupport@jeppesen.com](mailto:navdatatechsupport@jeppesen.com)

NavData Alerts are published to advise users of significant issues in Jeppesen navigation data which may affect flight operations or safety. Different avionics equipment and computer systems use and display NavData and data derived from NavData differently. End NavData users should consult with their Avionics Provider for definitive information on whether their system is affected by this Alert.