



## **!! URGENT !!**

**Date:** 23 May 2019

**Subject:** Frankfurt/Main, Germany (EDDF)  
ILS or LOC Rwy 25L [I25L] and [L25L]  
Cycle 1906

### ***Approach Procedure Identifiers Incorrect***

Jeppesen NavData for cycle 1906, effective 23 May 2019, contains an incorrect approach procedure name and identifier at Frankfurt/Main, Germany (EDDF).

Procedure ILS Z or LOC Z Rwy 25L [I25LZ] and [L25LZ] should read ILS or LOC Rwy 25L [I25L] and [L25L].

## **WE STRONGLY URGE YOU TO MAKE THIS INFORMATION AVAILABLE TO APPROPRIATE CREW MEMBERS OR CUSTOMERS IMMEDIATELY!**

Revised coding will appear in Jeppesen NavData for cycle 1907, effective 20 June 2019. Until then an entry will appear in the NavData Change Notices, and this Alert will be posted on the Jeppesen Web site: [Notices and Alerts](#).

Please refer to the Frankfurt/Main, Germany (EDDF) 11-6 chart, dated 17 May 19 (effective 23 May 19) for valid information.

If you have questions concerning this NavData Alert, please contact Jeppesen Technical Support at:  
+1-303-328-4445 (Western Hemisphere)  
+49 610 250 8175 (Eastern Hemisphere)  
E-mail: [navdatatechsupport@jeppesen.com](mailto:navdatatechsupport@jeppesen.com)

NavData Alerts are published to advise users of significant issues in Jeppesen navigation data which may affect flight operations or safety. Different avionics equipment and computer systems use and display NavData and data derived from NavData differently. End NavData users should consult with their Avionics Provider for definitive information on whether their system is affected by this Alert.