



!! URGENT !!

Date: 24 April 2018

Subject: Lubumbashi, DR of Congo
Lubumbashi Intl (FZQA)
Multiple Procedures
Cycle 1805

Procedure coding outdated

Jeppesen NavData for cycle 1805, effective 26 April 2018, contains outdated procedure coding for Lubumbashi Intl; Lubumbashi, DR of Congo (FZQA). AIP SUP 1/18 was received after the ICAO specified date for aeronautical information transmission. Therefore, the procedure changes are not contained in the 1805 database.

The following procedures have been completely revised and should not be used:

RNAV (GNSS) Rwy 07 [R07]
VOR/DME Rwy 07 [D07]

The following procedures are not contained in the 1805 database:

VOR Z Rwy 07 [S07-Z]
VOR Y RWY 07 [S07-Y]
ILS or LOC Z 07 [I07-Z]
ILS or LOC Y 07 [I07-Y]
ILS or LOC X 07 [I07-X]

WE STRONGLY URGE YOU TO MAKE THIS INFORMATION AVAILABLE TO APPROPRIATE CREW MEMBERS OR CUSTOMERS IMMEDIATELY!

Revised coding will appear in Jeppesen NavData for cycle 1806, effective 24 May 2018. Until then an entry will appear in the NavData Change Notices, and this Alert will be posted on the Jeppesen Web site: [Notices and Alerts](#).

If you have questions concerning this NavData Alert, please contact Jeppesen Technical Support at:
+1-303-328-4445 (Western Hemisphere)
+49 610 250 8175 (Eastern Hemisphere)
E-mail: navdatatechsupport@jeppesen.com

NavData Alerts are published to advise users of significant issues in Jeppesen navigation data which may affect flight operations or safety. Different avionics equipment and computer systems use and display NavData and data derived from NavData differently. End NavData users should consult with their Avionics Provider for definitive information on whether their system is affected by this Alert.