



JEPPESEN.
NavData® Alert

!! URGENT !!

Date: 22 May 2018

Subject: Jubail, Saudi Arabia
Jubail (OEJB)
VOR Rwy 17 [S17]
Cycle 1806

Missed Approach Holding incorrect

Jeppesen NavData for cycle 1806, effective 24 May 2018, contains an incorrect missed approach holding on VOR JBL on the VOR Rwy 17 [S17] at Jubail; Jubail, Saudi Arabia (OEJB).

The correct missed approach holding on VOR JBL: **inbound track 344 degrees, left turn.**

WE STRONGLY URGE YOU TO MAKE THIS INFORMATION AVAILABLE TO APPROPRIATE CREW MEMBERS OR CUSTOMERS IMMEDIATELY!

Revised coding will appear in Jeppesen NavData for cycle 1807, effective 21 Jun 2018. Until then an entry will appear in the NavData Change Notices, and this Alert will be posted on the Jeppesen Web site: [Notices and Alerts](#). Please refer to the Jubail, Saudi Arabia (OEJB) Chart 13-1 dated 18 MAY 18 (EFF 24 MAY) for valid information.

If you have questions concerning this NavData Alert, please contact Jeppesen Technical Support at:
+1-303-328-4445 (Western Hemisphere)
+49 610 250 8175 (Eastern Hemisphere)
E-mail: navdatatechsupport@jeppesen.com

NavData Alerts are published to advise users of significant issues in Jeppesen navigation data which may affect flight operations or safety. Different avionics equipment and computer systems use and display NavData and data derived from NavData differently. End NavData users should consult with their Avionics Provider for definitive information on whether their system is affected by this Alert.

OEJB_1806