



## !! URGENT !!

**Date:** 02 May 2019

**Subject:** Muscat, Oman  
Muscat Intl (OOMS)  
ILS Rwy 08L and LOC Rwy 08L  
Cycle 1905

***Waypoint incorrect***

Jeppesen NavData for cycle 1905, effective 25 April 2019, contains an incorrect waypoint on the ILS Rwy 08L and LOC Rwy 08L at Muscat Intl; Muscat, Oman (OOMS).

Waypoint **ITLAK** should read **M12WL** on ILS Rwy 08L and LOC Rwy 08L.

### **WE STRONGLY URGE YOU TO MAKE THIS INFORMATION AVAILABLE TO APPROPRIATE CREW MEMBERS OR CUSTOMERS IMMEDIATELY!**

Revised coding will appear in Jeppesen NavData for cycle 1906, effective 23 May 2019. Until then an entry will appear in the NavData Change Notices, and this Alert will be posted on the Jeppesen Web site: [Notices and Alerts](#). Please refer to the Muscat, Oman (OOMS) Chart 11-1, dated 5 OCT 18 (EFF 11 OCT 18) for valid information.

If you have questions concerning this NavData Alert, please contact Jeppesen Technical Support at:  
+1-303-328-4445 (Western Hemisphere)  
+49 610 250 8175 (Eastern Hemisphere)  
E-mail: [navdatatechsupport@jeppesen.com](mailto:navdatatechsupport@jeppesen.com)

NavData Alerts are published to advise users of significant issues in Jeppesen navigation data which may affect flight operations or safety. Different avionics equipment and computer systems use and display NavData and data derived from NavData differently. End NavData users should consult with their Avionics Provider for definitive information on whether their system is affected by this Alert.

OOMS\_1905