



!! URGENT !!

Date: 5 December 2018

Subject: Riyadh, Saudi Arabia
King Salman AB (OERY)
VOR Rwy 33 [S33]
Cycle 1813

FAF ident incorrect

Jeppesen NavData for cycle 1813, effective 6 December 2018, contains incorrect data for King Salman AB; Riyadh, Saudi Arabia (OERY). **Final Approach Fix** on VOR Rwy 33 [S33] should read **BOSUR (N243753.7 E0464606.0)**.

WE STRONGLY URGE YOU TO MAKE THIS INFORMATION AVAILABLE TO APPROPRIATE CREW MEMBERS OR CUSTOMERS IMMEDIATELY!

Revised coding will appear in Jeppesen NavData for cycle 1901, effective 3 January 2019. Until then an entry will appear in the NavData Change Notices, and this Alert will be posted on the Jeppesen Web site: [Notices and Alerts](#). Please refer to the King Salman AB; Riyadh, Saudi Arabia (OERY) 13-4 chart dated 30 NOV 18 (effective 6 December 2018) for valid information.

If you have questions concerning this NavData Alert, please contact Jeppesen Technical Support at:
+1-303-328-4445 (Western Hemisphere)
+49 610 250 8175 (Eastern Hemisphere)
E-mail: navdatatechsupport@jeppesen.com

NavData Alerts are published to advise users of significant issues in Jeppesen navigation data which may affect flight operations or safety. Different avionics equipment and computer systems use and display NavData and data derived from NavData differently. End NavData users should consult with their Avionics Provider for definitive information on whether their system is affected by this Alert.

OERY_1813