



## **!! URGENT !!**

**Date:** 26 December 2018

**Subject:** Kochi, Japan  
Kochi (RJOK)  
ILS Z or LOC Z Rwy 32  
Cycle 1901

*Procedure not useable*

Jeppesen NavData for cycle 1901, effective 3 January 2019, contains ILS Z or LOC Z Rwy 32. During the service to Localizer IKR, only the ILS Y or LOC Y Rwy 32 is authorized.

**THEREFORE, DO NOT USE THE ILS Z or LOC Z RWY 32 PROCEDURE IN CYCLE 1901 NAVDATA.**

**IF YOUR FMS DOES NOT HAVE MULTIPLE APPROACH INDICATORS, THEN DO NOT USE THE ILS or LOC RWY 32 PROCEDURE IN CYCLE 1901 NAVDATA.**

Revised coding will appear in Jeppesen NavData for cycle 1902, effective 31 January 2019. Until then an entry will appear in the NavData Change Notice, and this Alert will be posted on the Jeppesen Web site (<http://www.jeppesen.com/company/alerts/alerts.jsp>). Please refer to the KOCHI, JAPAN (11-2-0) chart dated 28 DEC 18, Eff 2 Jan for valid information.

**WE STRONGLY URGE YOU TO MAKE THIS INFORMATION AVAILABLE TO APPROPRIATE CREW MEMBERS OR CUSTOMERS IMMEDIATELY!**

If you have questions concerning this NavData Alert, please contact Jeppesen Technical Support at:

Phone: 1-303-328-4445

E-mail: [navdatatechsupport@jeppesen.com](mailto:navdatatechsupport@jeppesen.com)

NavData Alerts are published to advise users of significant issues in Jeppesen navigation data which may affect flight operations or safety. They are distributed to affected ARINC 424 NavData users (avionics companies and other raw data users) and airlines receiving NavData directly from Jeppesen. Alerts are not distributed by Jeppesen to individual airline, business aviation or general aviation pilots, but are available to them on the Jeppesen Web site, [www.jeppesen.com](http://www.jeppesen.com). Different avionics equipment and computer systems use and display NavData and data derived from NavData differently. Avionics users should consult with their database update service provider for definitive information on whether their system is affected by this Alert.