

Navigation Database Addendum

AIRAC 2110 – Issue 1

SUP EY 08/21 effective 26th May 2021

EYSA Siauliai Intl

APCHs RWY 32R; Runway 32R

RWY 32R threshold displacement of 455m is not included in database.

Vertical Guidance should not be used.
Coded APCHs do not lead to threshold.

Please disseminate this information to all affected crews

Lufthansa Systems
FMS Customer Support
Wednesday, 8th September 2021

All valid FSAs/NDAs are available on <http://fms-info.lhsystems.com>
For any inquiries, please contact fms.support@lhsystems.com

Navigation Database Addendum

AIRAC 2109 – Issue 10

SUP EY 08/21 effective 26th May 2021

EYSA Siauliai Intl

APCHs RWY 32R; Runway 32R

RWY 32R threshold displacement of 455m is not included in database.

Vertical Guidance should not be used.
Coded APCHs do not lead to threshold.

Please disseminate this information to all affected crews

Lufthansa Systems
FMS Customer Support
Wednesday, 8th September 2021

All valid FSAs/NDAs are available on <http://fms-info.lhsystems.com>
For any inquiries, please contact fms.support@lhsystems.com