



→ Home  
→ Site Map

Log out

Downloads

> Downloads



BULLETINS



CHANGE  
LOG



SERVICES



FEEDBACK



ORDER  
ARCHIVE



MY  
PROFILE

## : Vienna (Wien Schwechat) International Airport – ILS and LOC RWY 16 incorrect OEZ10 coordinates

« [Back](#)

**Date posted** 08/07/2021 12:22:31  
**Subject** FMS Navdata  
**Title** : Vienna (Wien Schwechat) International Airport – ILS and LOC RWY 16 incorrect OEZ10 coordinates  
**Data file**  
**Signed** Yes

**Cycle:** 2106

**Eff date:** 17<sup>th</sup> June 2021

**Country:** Austria

**Subject:** Vienna (Wien Schwechat) International Airport – ILS and LOC RWY 16 incorrect OEZ10 coordinates

**Source:** AIP 210618

**NAVBLUE Reference:** 210617

**Bulletin Published date:** 08 JULY 2021

*Please note that the following ERROR has been identified in NAVBLUE databases for cycle 2106.*

### Vienna (LOWW)

**CAUTION:** ILS and LOC RWY 16 are published and are **INCORRECT IN NAVBLUE DATABASES.**

Waypoint OEZ10 coordinates should read N47-57-23.10 E016-38-39.51.

*This change will be incorporated in NAVBLUE databases for cycle 2108.*