



→ Home
→ Site Map

Log out

Downloads

> Downloads



BULLETINS



CHANGE
LOG



SERVICES



FEEDBACK



ORDER
ARCHIVE



MY
PROFILE

OMITTED DATA NOTIFICATION BULLETIN.

« [Back](#)

Date posted 06/09/2021 12:56:48
Subject FMS Navdata
Title OMITTED DATA NOTIFICATION BULLETIN.
Data file
Signed Yes

Cycle: 2109

Eff date: 9th September 2021

OMITTED DATA NOTIFICATION BULLETIN.

NAVBLUE Reference: 210901

Bulletin Published date: 1st September 2021

Please note that the following information has not been incorporated into NAVBLUE databases for cycle 2109.

The below information is under state query and has been omitted from NAVBLUE databases until the query has been resolved.

Source: Spain (LEMI) (Corvera/Murcia International)

NOT IN NAVBLUE DATABASES: SID RESTU 1S – Design Architect is not within ARINC rules.

Source: Ethiopia (HAAB) (Addis Ababa Bole) AIP AMD 02/18

NOT IN NAVBLUE DATABASES: Published coordinates for NDB AB for HAAB not consistent with the location in operational notes.

Source: Bolivia AIP Amd 37-19

NOT IN NAVBLUE DATABASES: SLBJ RWY 01/19 updates from AIP Amd 37-19 not incorporated as awaiting state response concerning RWY length.

Source: Bolivia AIP Amd 37-19

NOT IN NAVBLUE DATABASES: SLOR RWY 01/19 updates from AIP Amd 37-19 not incorporated as awaiting state response concerning D.THR data.

Source: Bolivia AIP Amd 37-19

NOT IN NAVBLUE DATABASES: SLRY RWY 01/19 updates from AIP Amd 37-19 not incorporated as awaiting state response concerning D.THR data.

Source: Sudan AIP Supplement 10/19,11/19,12/19,13/19,14/19

NOT IN NAVBLUE DATABASES: We are waiting on a response from the state regarding the potential closure of parking stands S19, S20, S21, S30 and S42.

Source: DR Congo AIRAC AIP Supplement 05/19, 06/19, 07/19 and 10/19

NOT IN NAVBLUE DATABASES: NAVAID LUBUMBASHI (LUB) – Coordinate discrepancy
AIRAC AIP Supplement 8/19 and AIRAC AIP Supplement 9/19 states that the coordinates for LUB are S113543.17 E0273058.98 however current AIP publishes 15 AWYs with the VOR/DME LUB coordinates as S113607.85 E0273020.00.
Query has been raised for confirmation of correct coordinates.

-

Source: Iran (OIIB) AIRAC AIP Amd 03/20

NOT IN NAVBLUE DATABASES: Due to a pending state query the aerodrome and airspace information for OIIB has not been added to the database.

Source Indonesia AIRAC AMD Vol IV 44-2

NOT IN NAVBLUE DATABASES: RWY slope of $\pm 19\%$ on RWY 07/25 at WAYL not included due to outstanding state query.

Source: Indonesia AIRAC Amd 96/20

NOT IN NAVBLUE DATABASES: RWY 09/27 at WAMG has not been updated in Navblue databases. This is due to an ongoing query with the state.

Source: Democratic Republic of Congo (FZNP) AIP amendment 4-20

NOT IN NAVBLUE DATABASES: The change of THR coordinates on RWY 11/29 at FZNP has not been included in Navblue databases due to an outstanding state query.

Source: Mauritania (GQNS) ASECNA AIP amendment 11-20

NOT IN NAVBLUE DATABASES: The RWY length of 1600m for RWY 06/24 at GQNS has not been included in Navblue databases due to an outstanding state query.

Source: China AIP AMD 14/20

NOT IN NAVBLUE DATABASES: The ILS-DME 'IDD' at ZSHC has not been included in Navblue databases due to a duplication conflict in state information.