



!! URGENT !!

Date: 1 May 2018

Subject: Maringa, Brazil
Maringa Regl – Silvio Name Junior (SBMG)
RNAV (GNSS) Z Rwy 10 [R10-Z] or [P10-Z]
RNAV (GNSS) Z Rwy 28 [R28-Z] or [P28-Z]
Cycle 1805

Procedure Coding Incorrect

Jeppesen NavData for cycle 1805, effective 26 April 2018, contains incorrect procedure coding for the RNAV (GNSS) Z Rwy 10 [R10-Z] or [P10-Z] and RNAV (GNSS) Z Rwy 28 [R28-Z] or [P28-Z] procedures, at Maringa Regl – Silvio Name Junior; Maringa, Brazil (SBMG) for operators that **DO NOT** display the Approach Ident with a Multiple approach indicator (multi-code). If the procedure identifier of the RNAV (GNSS) Z Rwy 10 [R10-Z] or [P10-Z] displays as [RNV10] or [GPS10] or if the procedure identifier of the RNAV (GNSS) Z Rwy 28 procedure displays as [RNV28] or [GPS28] and they don't include the multi-code indicator "Z" in cycle 1805 NavData, the procedure coding is unusable.

Note: For operators that display the procedure identifier with a multiple approach indicator (multi-code), the procedure coding is correct and is usable. Examples of correct/usable procedure titles and procedure ids:

RNAV (GNSS) Z Rwy 10 [R10-Z] and RNAV (RNP) Y Rwy 10 [R10-Y]
RNAV (GNSS) Z Rwy 28 [R28-Z] and RNAV (RNP) Y Rwy 28 [R28-Y]

THEREFORE, DO NOT USE NAVDATA CODING FOR THE RNAV (GNSS) Z RWY 10 [R10-Z] OR [P10-Z] IF THE PROCEDURE IDENTIFIER IS DISPLAYED AS [RNV10] OR [GPS10] OR THE RNAV (GNSS) Z RWY 28 [R28-Z] OR [P28-Z] IF THE PROCEDURE IDENTIFIER IS DISPLAYED AS [RNV28] OR [GPS28] IN CYCLE 1805 NAVDATA.

Revised coding will appear in Jeppesen NavData for cycle 1806, effective 24 May 2018. Please refer to the Maringa Regl – Silvio Name Junior; Maringa, Brazil (SBMG) 12-1 chart dated 29 DEC 17, effective 4 Jan and the 12-2 chart dated 29 DEC 17, effective 4 Jan for valid information.

WE STRONGLY URGE YOU TO MAKE THIS INFORMATION AVAILABLE TO APPROPRIATE CREW MEMBERS OR CUSTOMERS IMMEDIATELY!

If you have questions concerning this NavData Alert, please contact Jeppesen Technical Support at:
Phone: 1-303-328-4445

E-mail: navdatatechsupport@jeppesen.com

NavData Alerts are published to advise users of significant issues in Jeppesen navigation data which may affect flight operations or safety. They are distributed to affected ARINC 424 NavData users (avionics companies and other raw data users) and airlines receiving NavData directly from Jeppesen. Alerts are not distributed by Jeppesen to individual airline, business aviation or general aviation pilots, but are available to them on the Jeppesen Web site, www.jeppesen.com. Different avionics equipment and computer systems use and display NavData and data derived from NavData differently. Avionics users should consult with their database update service provider for definitive information on whether their system is affected by this Alert.