



[→ Home](#)
[→ Site Map](#)

UNIVERSAL AVIONICSan **Elbit Systems** CompanyLogged in as Bob Holloway
of Universal Avionics Log out

Downloads

[> Downloads](#)

BULLETINS



CHANGE LOG



SERVICES



FEEDBACK

ORDER
ARCHIVE

MY PROFILE

WARSAWA/MODLIN (EPMO) Incorrect Vertical Angle RNP RWY 08.

[« Back](#)

Date posted	11/10/2021 15:18:35
Subject	FMS Navdata
Title	WARSAWA/MODLIN (EPMO) Incorrect Vertical Angle RNP RWY 08.
Data file	
Signed	Yes

Cycle 2110

Eff date 7th Oct 2021

Country: POLAND.

Subject: WARSAWA/MODLIN (EPMO) Incorrect Vertical Angle RNP RWY 08.

Source: Poland AIP 211007.

NAVBLUE Reference: 211007

Bulletin Published date: 11 OCTOBER 2021

Please note that the following ERROR has been identified in NAVBLUE databases for cycle 2110.

WARSAWA/MODLIN (EPMO)

CAUTION: RNP APPROACH RWY 08 contains a vertical angle of 3.02° from OGRAR. The vertical angle should start at M0823.

These changes will be incorporated in NAVBLUE databases for cycle 2111.