



## **!! URGENT !!**

**Date:** 7 January 2019

**Subject:** Bridgeport, Conn  
Sikorsky Meml (KBDR)  
RNAV (GPS) Rwy 29  
Cycle 1901

### ***Missed Approach Hold***

Jeppesen NavData for cycle 1901, effective 3 January 2019, contains incorrect missed approach hold turn direction at ZONKO Waypoint on the RNAV (GPS) Rwy 29.

**THE CORRECT MISSED APPROACH HOLD AT ZONKO WAYPOINT IS 064 DEGREES INBOUND, RIGHT TURNS.**

Revised coding will appear in Jeppesen NavData for cycle 1902, effective 31 January 2019. Until then an entry will appear in the NavData Change Notices, and this Alert will be posted on the Jeppesen Web site (<http://www.jeppesen.com/company/alerts/alerts.jsp>). Please refer to the Bridgeport, Conn (KBDR) 12-3 chart dated 28 DEC 18 (Eff 3 Jan) for valid information.

**WE STRONGLY URGE YOU TO MAKE THIS INFORMATION AVAILABLE TO APPROPRIATE CREW MEMBERS OR CUSTOMERS IMMEDIATELY!**

If you have questions concerning this NavData Alert, please contact Jeppesen Technical Support at:  
Phone: 1-303-328-4445  
E-mail: [navdatatechsupport@jeppesen.com](mailto:navdatatechsupport@jeppesen.com)

NavData Alerts are published to advise users of significant issues in Jeppesen navigation data which may affect flight operations or safety. They are distributed to affected ARINC 424 NavData users (avionics companies and other raw data users) and airlines receiving NavData directly from Jeppesen. Alerts are not distributed by Jeppesen to individual airline, business aviation or general aviation pilots, but are available to them on the Jeppesen Web site, [www.jeppesen.com](http://www.jeppesen.com). Different avionics equipment and computer systems use and display NavData and data derived from NavData differently. Avionics users should consult with their database update service provider for definitive information on whether their system is affected by this Alert.