



JEPPESEN[®]
NavData[®] Alert

!! URGENT !!

Date: 6 July 2021

Subject: Kingston, Jamaica
Norman Manley Intl (MKJP)
ILS Rwy 12

Cycles 2106 & 2107

Incorrect Missed Approach

Jeppesen NavData for cycle 2106, effective 17 June 2021, and cycle 2107, effective 15 July 2021, contains incorrect missed approach coding.

The missed approach coding should be: Climb to 1000'. Turn RIGHT to heading 225 degrees to intercept 17.0 DME Arc MLY VOR at 4000' to KEYNO (D17.0 MLY VOR). Thence hold at SALOC (D7.4 MLY VOR).

Revised coding will appear in Jeppesen NavData for cycle 2108, effective 12 August 2021. Until then an entry will appear in the NavData Change Notices, and this Alert will be posted on the Jeppesen Web site: [Notices and Alerts](#).

Please refer to the Kingston, Jamaica; Norman Manley Intl (MKJP) 11-1 chart dated 12 JUN 20 (effective 18 Jun) for valid information.

If you have questions concerning this NavData Alert, please contact Jeppesen Technical Support at:
+1-303-328-4445 (Western Hemisphere)
+49 610 250 8175 (Eastern Hemisphere)
E-mail: navdatatechsupport@jeppesen.com

NavData Alerts are published to advise users of significant issues in Jeppesen navigation data which may affect flight operations or safety. Different avionics equipment and computer systems use and display NavData and data derived from NavData differently. End NavData users should consult with their Avionics Provider for definitive information on whether their system is affected by this Alert.