



!! URGENT !!

Date: 7 September 2021

Subject: Pearce, WA, Australia
Pearce (YPEA)
ILS-Z Rwy 36R
Cycle 2109

Procedure identifier incorrect

Jeppesen NavData for cycle 2109, effective 9 September 2021, contains incorrect data at Pearce; Pearce, WA, Australia (YPEA). RAAF AIPAB effective 9 September 2021 was received after the ICAO specified date for aeronautical information publication.

Approach procedure **ILS-Z Rwy 36R** should read **ILS-X Rwy 36R**.

WE STRONGLY URGE YOU TO MAKE THIS INFORMATION AVAILABLE TO APPROPRIATE CREW MEMBERS OR CUSTOMERS IMMEDIATELY!

Revised coding will appear in Jeppesen NavData for cycle 2110, effective 7 October 2021. Until then an entry will appear in the NavData Change Notices, and this Alert will be posted on the Jeppesen Web site: [Notices and Alerts](#).

Please refer to the Pearce, WA, Australia (YPEA) 11-4-0 chart dated 17 SEP 21 for valid information.

If you have questions concerning this NavData Alert, please contact Jeppesen Technical Support at:
+1-303-328-4445 (Western Hemisphere)
+49 610 250 8175 (Eastern Hemisphere)
E-mail: navdatasupport@boeing.com

NavData Alerts are published to advise users of significant issues in Jeppesen navigation data which may affect flight operations or safety. Different avionics equipment and computer systems use and display NavData and data derived from NavData differently. End NavData users should consult with their Avionics Provider for definitive information on whether their system is affected by this Alert.