



→ Home
→ Site Map

Log out

Downloads

> Downloads



BULLETINS



CHANGE
LOG



SERVICES



FEEDBACK



ORDER
ARCHIVE



MY
PROFILE

LATE SOURCE NOTIFICATION BULLETIN PT2

[« Back](#)

Date posted	10/08/2021 12:26:12
Subject	FMS Navdata
Title	LATE SOURCE NOTIFICATION BULLETIN PT2
Data file	
Signed	Yes

Cycle 2108

Eff date: 12th August 2021

LATE SOURCE NOTIFICATION BULLETIN

NAVBLUE Reference: 210803 Part 2

Bulletin Published date: 10 AUGUST 2021

Please note that the following information was received too late to be incorporated into NAVBLUE databases for cycle 2108.

CORUMBA INTL (SBCR)

SID

NEGRO 2A: New procedure added.

MODA, NEGRO, REALY: Procedures are suspended.

MARECHAL RONDON INTL (SBCY)

RWY 17/35

APPROACH

VOR Z 17: New procedure added.

VOR 17: Procedures are suspended.

AFONSO PENA INTL (SBCT)

LOC/ILS RWY 33 ITA

SID

OMNI: New OMNI directional procedure added.

APPROACH

ILS X 33, LOC X 33, ILS Z 15: Procedures are suspended.

DOURADOS (SBDO)

SID

OMNI: New OMNI directional procedure added.

FERNANDO DE NORONH (SBFN)

SID

OMNI: New OMNI directional procedure added.

MOTLI 1A, NISBU 1A: Procedures are suspended.

MOTLI 1B, MOTLI 1C, NISBU 1B, NISBU 1C: New procedure added.

APPROACH

VOR 12: VAR changed to 19W°, Outbound distance in FNR transition changed to D8 FNR, Outbound course in FNR transition changed to 337°, FAT and CA course in MISAP segment changed to 125°, CA ALT in MISAP segment changed to 3000ft+ and speed 250kt- added on CA leg, INBD course of HP changed to 337°.

RNP 12: VAR changed to 19W°, FAT and CA course in MISAP segment changed to 114°, INBD course of HP changed to 294°.

RNP 30: VAR changed to 19W°, FAT and CA course in MISAP segment changed to 294°, INBD course of HP changed to 114°.

PINTO MARTINS INTL (SBFZ)

RWY 13/31

APPROACH

RNP 31: ALT at FZ384 changed to 2020ft+, ALT at MAPT changed to 115ft@.

VOR DME 31: Transition FNR removed, new transitions UMBAR, NETLA added, IF changed to UDOTO with 2000ft+ ALT, FAF changed to ILMIX with 1710ft+ ALT, MAPT ALT changed to 115ft@, Missed Approach completely revised.

VOR 31: Procedures are suspended.

PRESIDENTE ITAMAR FRANCO (SBZM)

SID

OMNI: New OMNI directional procedure added.

SURNA 1A, SURNA 1B, VUROS 1A, VUROS 1B: New procedures added.

SURNA 1, BBC1, TOGON 1: Procedures are suspended.

APPROACH

RNP 08: WP ZM003 changed to ZM009, VAR changed to 23W°. ALT at MAPT changed to 1379ft@.

RNP 26: ALT at ZM031 changed to 2970ft, VAR changed to 23W°. ALT at MAPT changed to 1377ft@, INBD course of HP changed to 187°.

VIRACOPOS INTL (SBKP)

STAR

ILSOR 2A, ILSOR 1D: Procedures are suspended.

APPROACH

ILS V 15, LOC V 15, RNAV Y 15, RNAV Y 33: Procedures are suspended.

JORGE AMADO (SBIL)

SID

BIVOV 1A, BIVOV 1B, DINER 1A, ESLIB 1A, MAPVU 1, DENDE 1A, DENDE 1B, RAIRA 1A, RAIRA 1B, SGR 1: Procedures are suspended.