

Navigation Database Addendum

AIRAC 2109 – Issue 19

SUP SC S12/21 **effective 26th September 2021 (effective date revised by authority)**

SCCI Punta Arenas / Carlos Ibanez del Campo Intl

Runway 12/30

- Due to late receipt of document, **RWY 12 THR displacement of 1200m not included** in NavDB, virtual RWY 13 THR coordinates should read S53-00-20.41 W070-51-24.98.
- Vertical guidance should **not** be used.
- Procedures for RWY13/30 only available for CAT A,B

Navdata will be updated effective AIRAC cycle 2110.

Please disseminate this information to all affected crews

Lufthansa Systems
FMS Customer Support
Thursday, 23rd September 2021

All valid FSAs/NDAs are available on <http://fms-info.lhsystems.com>
For any inquiries, please contact fms.support@lhsystems.com